

Standard Operating Procedure for Major Alarm

ALARM_2375 on Ericsson Access Switch Node

Ericsson-Access-Mumbai-MH-40

Node: Ericsson-Access-Mumbai-MH-40 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_2375

Description

This SOP outlines the steps to identify and resolve a Major Alarm ALARM_2375 on the Ericsson Access Switch Node Ericsson-Access-Mumbai-MH-40.

Potential Root Causes

Cause	Probability
Invalid or corrupted configuration files	High
Hardware failure or malfunction	Medium
Software or firmware issues	Low

Diagnostic Commands

```
show alarm history
show system resource utilization
show interface
show ip interface brief
show ip route
```

Resolution Steps

- Step 1: {'Step': '1. Check the alarm history to identify the time of occurrence and any previous alarms.', 'Action': 'Run the command: show alarm history'}
- Step 2: {'Step': '2. Verify the system resource utilization.', 'Action': 'Run the command: show system resource utilization'}
- Step 3: {'Step': '3. Check the interface status and configuration.', 'Action': 'Run the command: show interface '}
- Step 4: {'Step': '4. Verify the IP interface configuration.', 'Action': 'Run the command: show ip interface brief'}
- Step 5: {'Step': '5. Verify the IP routing table.', 'Action': 'Run the command: show ip route'}

Step 6: {'Step': '6. If the issue persists, try restarting the affected interface or system.', 'Action': 'Run the command: reload or reload system'}

Step 7: {'Step': '7. If the issue is hardware-related, contact the vendor for repair or replacement.', 'Action': 'Contact Ericsson support team'}

Post-Check Verification

```
show alarm history
show interface
show ip interface brief
show ip route
```