

SOP: Resolving Ericsson Access Switch Alarm

ALARM_2536 in Mumbai Node

Node: Ericsson-Access-Mumbai-MH-40 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_2536

Description

This SOP outlines the steps to resolve a Major alarm on Ericsson Access Switch Node Ericsson-Access-Mumbai-MH-40 with Alarm Code ALARM_2536.

Potential Root Causes

Cause	Probability
Hardware Failure in the Access Switch	High
Software Bug or Misconfiguration	Medium
Power Issues or Unstable Power Supply	Low

Diagnostic Commands

```
show alarm details ALARM_2536
show system status
show interface statistics all
```

Resolution Steps

- Step 1: {'Step': '1. Power Cycle the Access Switch', 'Description': 'Cycle the power to the Access Switch Node Ericsson-Access-Mumbai-MH-40 to rule out power-related issues.', 'Command': 'power cycle Ericsson-Access-Mumbai-MH-40'}
- Step 2: {'Step': '2. Check for Hardware Faults', 'Description': 'Perform a visual inspection of the Access Switch hardware and check for any signs of physical damage or malfunction.', 'Command': 'show hw faults'}
- Step 3: {'Step': '3. Verify Software Configuration', 'Description': 'Verify the software configuration of the Access Switch Node Ericsson-Access-Mumbai-MH-40 to ensure it matches the recommended settings.', 'Command': 'show config'}
- Step 4: {'Step': '4. Reboot the Access Switch', 'Description': 'Reboot the Access Switch Node Ericsson-Access-Mumbai-MH-40 to ensure a clean startup.', 'Command': 'reboot Ericsson-Access-Mumbai-MH-40'}
- Step 5: {'Step': '5. Check for Software Updates', 'Description': 'Check the Ericsson website for any available software updates for the Access Switch Node Ericsson-Access-Mumbai-MH-40.', 'Command': 'show sw version'}

Post-Check Verification

```
show alarm details ALARM_2536  
show system status  
show interface statistics all
```