

# Ericsson Access Switch Alarm Resolution SOP

**Node:** Ericsson-Access-Mumbai-MH-40 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM\_4178

## Description

This SOP outlines the steps to diagnose and resolve the ALARM\_4178 issue on the Ericsson Access Switch Node ID: Ericsson-Access-Mumbai-MH-40.

## Potential Root Causes

| Cause                           | Probability |
|---------------------------------|-------------|
| Faulty Optical Fiber Connection | High        |
| Incorrect Configuration         | Medium      |
| Hardware Failure                | Low         |

## Diagnostic Commands

```
show system redundancy
show optics status
show config | inc optical-fiber
```

## Resolution Steps

- Step 1: {'Step': 1, 'Action': 'Verify Optical Fiber Connection', 'Description': 'Check the physical connection of the optical fiber and ensure it is secure.', 'CLI\_Commands': []}
- Step 2: {'Step': 2, 'Action': 'Reconfigure Optical Fiber Settings', 'Description': 'Reconfigure the optical fiber settings using the CLI command: "configure optical-fiber "', 'CLI\_Commands': ['configure optical-fiber ']}
- Step 3: {'Step': 3, 'Action': 'Replace Faulty Hardware', 'Description': 'Replace the faulty hardware component.', 'CLI\_Commands': []}

## Post-Check Verification

```
show system redundancy
show optics status
show config | inc optical-fiber
```