

Ericsson Access Switch ALARM_5314 Resolution SOP

Node: Ericsson-Access-Mumbai-MH-40 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_5314

Description

This Standard Operating Procedure outlines the steps to diagnose and resolve the ALARM_5314: Critical Alarm on Ericsson Access Switch Node Ericsson-Access-Mumbai-MH-40.

Potential Root Causes

Cause	Probability
Hardware failure in the switch's power supply unit (PSU)	High
Software issue with the switch's control plane	Medium
Environmental factors affecting the switch's operation (e.g. power supply issues, overheating)	Low

Diagnostic Commands

```
show system resource mem
show system resource cpu
show system alarm detail
show system redundancy status
```

Resolution Steps

- Step 1: {'Step': 'Power cycle the switch', 'Action': "Use the CLI command 'system halt' followed by 'system reboot' to power cycle the switch."}
- Step 2: {'Step': 'Replace the PSU', 'Action': 'Identify the faulty PSU and replace it with a spare unit. Ensure the new PSU is properly seated and configured.'}
- Step 3: {'Step': "Update the switch's software", 'Action': "Use the CLI command 'install software' to update the switch's software to the latest version."}
- Step 4: {'Step': 'Verify environmental conditions', 'Action': "Check the switch's operating temperature, humidity, and power supply conditions to ensure they are within the recommended ranges."}

Post-Check Verification

```
show system alarm detail
show system resource mem
```

```
show system resource cpu  
show system redundancy status
```