

Ericsson Access Switch Alarm SOP

Node: Ericsson-Access-Mumbai-MH-40 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_7386

Description

Alarm Code: ALARM_7386 - Severity: Warning on Ericsson Access Switch Node ID: Ericsson-Access-Mumbai-MH-40

Potential Root Causes

Cause	Probability
High CPU Utilization due to Software Bug	High
Misconfigured QoS Settings	Medium
Hardware Failure	Low

Diagnostic Commands

```
show cpu utilization
show qos settings
show hardware status
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU Utilization', 'Action': 'Run show cpu utilization command to identify high CPU usage', 'CLI_Command': 'show cpu utilization'}
- Step 2: {'Step': '2. Check QoS Settings', 'Action': 'Verify QoS settings are correctly configured', 'CLI_Command': 'show qos settings'}
- Step 3: {'Step': '3. Check Hardware Status', 'Action': 'Verify hardware status using show hardware status command', 'CLI_Command': 'show hardware status'}
- Step 4: {'Step': '4. Clear CPU Utilization Cache', 'Action': 'Clear CPU utilization cache using clear cpu utilization command', 'CLI_Command': 'clear cpu utilization'}
- Step 5: {'Step': '5. Reconfigure QoS Settings', 'Action': 'Reconfigure QoS settings to correct misconfiguration', 'CLI_Command': 'config qos settings'}
- Step 6: {'Step': '6. Replace Hardware (if necessary)', 'Action': 'Replace hardware if hardware failure is confirmed', 'CLI_Command': ''}

Post-Check Verification

```
show cpu utilization
```

```
show qos settings  
show hardware status
```