

Standard Operating Procedure for Resolving ALARM_9111 on Ericsson Access Switch in Mumbai

Node: Ericsson-Access-Mumbai-MH-40 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_9111

Description

This SOP outlines the steps to diagnose and resolve ALARM_9111, a minor alarm indicating a potential issue on Ericsson Access Switch Node ID: Ericsson-Access-Mumbai-MH-40.

Potential Root Causes

Cause	Probability
Incorrect configuration of the Access Switch	High
Hardware malfunction due to power supply issues	Medium
Software bug or upgrade failure	Low

Diagnostic Commands

```
show alarm brief
show system status
show hardware temperature
show software version
```

Resolution Steps

- Step 1: {'Step': '1. Check the alarm status and configuration', 'Action': "Run 'show alarm brief' command to identify the alarm source and verify the configuration."}
- Step 2: {'Step': '2. Verify power supply status', 'Action': "Run 'show system status' command to check the power supply status and ensure it's functioning correctly."}
- Step 3: {'Step': '3. Check hardware temperature', 'Action': "Run 'show hardware temperature' command to check the hardware temperature and ensure it's within the normal operating range."}
- Step 4: {'Step': '4. Verify software version', 'Action': "Run 'show software version' command to check the software version and ensure it's up-to-date."}
- Step 5: {'Step': '5. Reboot the Access Switch', 'Action': "Run 'reboot' command to reboot the Access Switch and clear any temporary issues."}
- Step 6: {'Step': '6. Verify the alarm is cleared', 'Action': "Run 'show alarm brief' command to verify the alarm is cleared."}

Post-Check Verification

```
show alarm brief
show system status
show hardware temperature
show software version
```