

Standard Operating Procedure for Ericsson Access Switch ALARM_2119 in Mumbai

Node: Ericsson-Access-Mumbai-MH-46 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_2119

Description

ALARM_2119 is a minor alarm indicating a potential issue with the Ericsson Access Switch in Mumbai. This SOP outlines the procedures to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Hardware Failure in the Ericsson Access Switch	High
Software Glitch in the Ericsson Access Switch	Medium
Environmental Factors affecting the Ericsson Access Switch	Low

Diagnostic Commands

```
show tech support
show system resource
show interface status
```

Resolution Steps

- Step 1: {'Step': '1. Run the show tech support command to gather system information.', 'Action': "Issue the command 'show tech support' on the Ericsson Access Switch."}
- Step 2: {'Step': '2. Check the system resource usage.', 'Action': "Issue the command 'show system resource' on the Ericsson Access Switch."}
- Step 3: {'Step': '3. Verify the interface status.', 'Action': "Issue the command 'show interface status' on the Ericsson Access Switch."}
- Step 4: {'Step': '4. Replace the faulty hardware component.', 'Action': 'Identify and replace the faulty hardware component in the Ericsson Access Switch.'}
- Step 5: {'Step': '5. Restart the Ericsson Access Switch.', 'Action': "Issue the command 'restart' on the Ericsson Access Switch."}

Post-Check Verification

```
show system resource
```

```
show interface status  
show tech support
```