

Ericsson Access Switch ALARM_3067 Minor Alarm SOP

Node: Ericsson-Access-Mumbai-MH-46 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_3067

Description

ALARM_3067 is a Minor alarm indicating a software error on Ericsson Access Switch Node ID: Ericsson-Access-Mumbai-MH-46.

Potential Root Causes

Cause	Probability
Software mismatch between Node B and the RNC	Medium
Incorrect configuration or parameters set for the Node B	Low
Corrupted or outdated Node B software	High

Diagnostic Commands

```
show node-b status
show node-b config
show node-b log error
show node-b version
```

Resolution Steps

- Step 1: {'Step': 'Verify the software versions of Node B and RNC', 'Action': 'run "show node-b version" and "show rnc version" commands to ensure they match'}
- Step 2: {'Step': 'Check the node B configuration', 'Action': 'run "show node-b config" command to verify the parameters are correctly set'}
- Step 3: {'Step': 'Update the Node B software', 'Action': 'run "install node-b software " command to update the software'}
- Step 4: {'Step': 'Reboot the Node B', 'Action': 'run "reboot node-b" command to restart the Node B'}

Post-Check Verification

```
show node-b status
show node-b config
show node-b log error
```