

Ericsson Access Switch Alarm Resolution SOP

(ALARM_3389)

Node: Ericsson-Access-Mumbai-MH-46 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_3389

Description

This SOP outlines the steps to diagnose, resolve, and verify a Minor Alarm (ALARM_3389) on Ericsson Access Switch Node ID: Ericsson-Access-Mumbai-MH-46.

Potential Root Causes

Cause	Probability
Hardware failure in the line card or port	Medium
Software issue in the switch's operating system	Low
Misconfigured interface or port settings	Medium

Diagnostic Commands

```
show tech-support | include ALARM_3389
show log | include ALARM_3389
show interface GigabitEthernet 0/0/0 | include errors
show port stats | include GigabitEthernet 0/0/0
```

Resolution Steps

- Step 1: {'Step': "1. Check the switch's log files for any error messages related to the alarm.", 'Action': "Run the command 'show log | include ALARM_3389' to view the log entries.", 'CLI_Command': 'show log | include ALARM_3389'}
- Step 2: {'Step': "2. Verify the hardware and software configurations of the affected line card or port.", 'Action': "Run the command 'show tech-support | include ALARM_3389' to view the technical support information.", 'CLI_Command': 'show tech-support | include ALARM_3389'}
- Step 3: {'Step': "3. Check the interface and port settings for any misconfigurations.", 'Action': "Run the command 'show interface GigabitEthernet 0/0/0 | include errors' to view the interface statistics.", 'CLI_Command': 'show interface GigabitEthernet 0/0/0 | include errors'}
- Step 4: {'Step': "4. Clear the alarm using the 'clear alarm' command.", 'Action': "Run the command 'clear alarm ALARM_3389' to clear the alarm.", 'CLI_Command': 'clear alarm ALARM_3389'}

Post-Check Verification

```
show log | include ALARM_3389
show tech-support | include ALARM_3389
show interface GigabitEthernet 0/0/0 | include errors
show port stats | include GigabitEthernet 0/0/0
```