

Standard Operating Procedure for Ericsson Access Switch ALARM_5189 in Mumbai

Node: Ericsson-Access-Mumbai-MH-46 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_5189

Description

This SOP outlines the steps to diagnose and resolve ALARM_5189, a warning alarm on Ericsson Access Switch Node ID Ericsson-Access-Mumbai-MH-46.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Excessive Traffic	Medium
Software Bug	Low

Diagnostic Commands

```
show cpu utilization
show traffic statistics
show system resources
show software versions
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU Utilization and Traffic Statistics', 'Action': "Run the commands 'show cpu utilization' and 'show traffic statistics' to identify any issues."}
- Step 2: {'Step': '2. Adjust System Resources (if necessary)', 'Action': "Run the command 'set system resources ' to adjust the system resources. Consult the user manual for details."}
- Step 3: {'Step': '3. Restart the Node (if necessary)', 'Action': "Run the command 'reset system' to restart the node. This will resolve the issue if it was caused by a software bug."}
- Step 4: {'Step': '4. Upgrade the Software (if necessary)', 'Action': "Run the command 'upgrade software' to upgrade the software to the latest version. Consult the user manual for details."}

Post-Check Verification

```
show cpu utilization
show traffic statistics
```

```
show system resources
show software versions
```