

Ericsson Access Switch Alarm SOP - ALARM_6176

Node: Ericsson-Access-Mumbai-MH-46 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_6176

Description

Minor alarm triggered on Ericsson Access Switch Node ID: Ericsson-Access-Mumbai-MH-46 due to vendor-specific issue.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Configuration issue with routing protocol	Medium
Hardware issue with port or interface	Low

Diagnostic Commands

```
show cpu utilization
show routing protocol statistics
show interface status
show port statistics
```

Resolution Steps

- Step 1: {'Step': '1. Verify CPU utilization', 'Action': 'Run command: show cpu utilization', 'Expected Output': 'CPU utilization below 80%'}
- Step 2: {'Step': '2. Check routing protocol configuration', 'Action': 'Run command: show routing protocol statistics', 'Expected Output': 'No configuration issues found'}
- Step 3: {'Step': '3. Check port or interface status', 'Action': 'Run command: show interface status', 'Expected Output': 'Port or interface is operational'}
- Step 4: {'Step': '4. Clear port or interface counters', 'Action': 'Run command: clear port statistics interface ', 'Expected Output': 'Port or interface statistics cleared'}
- Step 5: {'Step': '5. Verify alarm status', 'Action': 'Run command: show alarm status', 'Expected Output': 'Alarm cleared'}

Post-Check Verification

```
show cpu utilization
show routing protocol statistics
```

```
show interface status
show port statistics
show alarm status
```