

Ericsson Access Switch Alarm Resolution SOP

Node: Ericsson-Access-Mumbai-MH-46 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_7830

Description

This SOP outlines the steps to diagnose and resolve the ALARM_7830 (Minor) on the Ericsson-Access-Mumbai-MH-46 access switch.

Potential Root Causes

Cause	Probability
Incorrect configuration of the access switch	Medium
Hardware failure in the access switch	Low
Software issue with the access switch firmware	Medium

Diagnostic Commands

```
show system status
show access-switch configuration
show hardware status
```

Resolution Steps

- Step 1: {'Step': 'Verify the access switch configuration', 'Action': "Use the command 'show access-switch configuration' to verify that the configuration is correct.", 'CLI_Command': 'show access-switch configuration'}
- Step 2: {'Step': 'Check for hardware issues', 'Action': "Use the command 'show hardware status' to verify that there are no hardware issues.", 'CLI_Command': 'show hardware status'}
- Step 3: {'Step': 'Check for software issues', 'Action': 'Verify that the access switch firmware is up-to-date and check for any software issues.', 'CLI_Command': 'show software status'}
- Step 4: {'Step': 'Reboot the access switch', 'Action': 'Reboot the access switch to resolve any software issues.', 'CLI_Command': 'reboot system'}

Post-Check Verification

```
show system status
show access-switch configuration
show hardware status
```