

Ericsson Access Switch ALARM_3661 Minor Alarm SOP

Node: Ericsson-Access-Mumbai-MH-52 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_3661

Description

This SOP outlines the steps for resolving ALARM_3661 on Ericsson Access Switch at Node ID: Ericsson-Access-Mumbai-MH-52.

Potential Root Causes

Cause	Probability
Incorrect configuration or settings	High
Hardware failure or malfunction	Medium
Software issue or bug	Low

Diagnostic Commands

```
show alarm details
show system status
show interface
debug
```

Resolution Steps

- Step 1: {'Step': '1. Check the alarm history for similar alarms', 'Action': 'show alarm history'}
- Step 2: {'Step': '2. Verify the configuration and settings', 'Action': 'show configuration '}
- Step 3: {'Step': '3. Check for hardware issues', 'Action': 'show system status'}
- Step 4: {'Step': '4. Update software or firmware if necessary', 'Action': 'install software '}
- Step 5: {'Step': '5. Reboot the system', 'Action': 'reboot'}

Post-Check Verification

```
show alarm details
show system status
show interface
show configuration
```