

Ericsson Access Switch SOP for ALARM_6410

Node: Ericsson-Access-Mumbai-MH-52 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_6410

Description

This SOP covers the steps to diagnose and resolve a Major Alarm (ALARM_6410) on Ericsson Access Switch Node ID: Ericsson-Access-Mumbai-MH-52.

Potential Root Causes

Cause	Probability
Optical fiber cut or damage	High
Hardware failure in the access switch	Medium
Software bug or configuration issue	Low

Diagnostic Commands

```
show interface optics
show system status
show hardware status
show system logs
show configuration
```

Resolution Steps

- Step 1: {'Step': 'Verify the physical connections and cables', 'Action': 'Check for any loose or damaged cables, and reconnect as necessary.'}
- Step 2: {'Step': 'Run a diagnostic test on the affected interface', 'Action': 'Use the command: "test interface " to run a diagnostic test.'}
- Step 3: {'Step': 'Reset the access switch', 'Action': 'Use the command: "reset system" to reboot the access switch.'}
- Step 4: {'Step': 'Check the system logs for any error messages', 'Action': 'Use the command: "show system logs" to view the system logs.'}
- Step 5: {'Step': 'Reconfigure the access switch if necessary', 'Action': 'Use the command: "config terminal" to enter configuration mode, and then make any necessary changes.'}

Post-Check Verification

```
show interface optics
```

```
show system status  
show hardware status  
show system logs
```