

Ericsson Access Switch Alarm Handling SOP

(ALARM_7841)

Node: Ericsson-Access-Mumbai-MH-52 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_7841

Description

ALARM_7841 is a Major alarm on Ericsson Access Switch indicating a critical system failure. This SOP outlines the procedures to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Hardware failure in the switch	High
Software bug or configuration issue	Medium
Power supply or environmental issue	Low

Diagnostic Commands

```
show tech support diagnose
show tech support hardware
show tech support software
show power supply
```

Resolution Steps

- Step 1: {'Step': 'Power cycle the switch', 'Description': 'Power off the switch, wait for 10 seconds, and then power it on again.', 'CLI_Command': ' power off'}
- Step 2: {'Step': 'Run a hardware diagnostic test', 'Description': '"Use the 'show tech support diagnose' command to run a hardware diagnostic test."', 'CLI_Command': 'show tech support diagnose'}
- Step 3: {'Step': 'Check for software updates', 'Description': 'Check if there are any software updates available for the switch.', 'CLI_Command': 'show software version'}
- Step 4: {'Step': 'Reconfigure the switch', 'Description': 'Reconfigure the switch to default settings and then restore the original configuration.', 'CLI_Command': 'configure default'}

Post-Check Verification

```
show tech support diagnose
show power supply
```

```
show software version
```