

Ericsson Access Switch Alarm Resolution SOP (ALARM_8592)

Node: Ericsson-Access-Mumbai-MH-52 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_8592

Description

This SOP outlines the steps to diagnose and resolve the ALARM_8592, a major alarm on Ericsson Access Switch Node ID Ericsson-Access-Mumbai-MH-52.

Potential Root Causes

Cause	Probability
Optical Interface Failure	High
Software Crash or Hang	Medium
Hardware Failure (e.g., Power Supply, Fan)	Low

Diagnostic Commands

```
show interface optics
show system resources
show system software status
show system hardware status
```

Resolution Steps

- Step 1: {'Step': 'Check the alarm log for relevant information', 'Action': 'show alarm log'}
- Step 2: {'Step': 'Verify the optical interface status', 'Action': 'show interface optics'}
- Step 3: {'Step': 'Check system resources (e.g., memory, CPU usage)', 'Action': 'show system resources'}
- Step 4: {'Step': 'Reboot the node if software crash or hang is suspected', 'Action': 'system reboot'}
- Step 5: {'Step': 'Replace failed hardware components', 'Action': 'replace power supply/fan'}

Post-Check Verification

```
show interface optics
show system resources
show system software status
```

```
show system hardware status
```