

Ericsson Access Switch SOP for ALARM_9713

Node: Ericsson-Access-Mumbai-MH-52 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_9713

Description

This SOP outlines the steps to diagnose and resolve the ALARM_9713 on the Ericsson Access Switch
Node ID: Ericsson-Access-Mumbai-MH-52.

Potential Root Causes

Cause	Probability
High CPU utilization due to software issues	High
Hardware failure in the access switch	Medium
Configuration issues or conflicts	Low

Diagnostic Commands

```
show cpu utilization
show processes
show interfaces
show system info
show alarms
```

Resolution Steps

- Step 1: { 'Step': 'Restart the access switch', 'CLI_Command': 'reboot' }
- Step 2: { 'Step': 'Update software to the latest version', 'CLI_Command': 'install software ' }
- Step 3: { 'Step': 'Replace faulty hardware components', 'Action': 'Perform hardware replacement' }
- Step 4: { 'Step': 'Check and rectify configuration issues', 'CLI_Command': 'show configuration' }

Post-Check Verification

```
show cpu utilization
show processes
show interfaces
show system info
show alarms
```