

Standard Operating Procedure for Ericsson PE

Bangalore Node ID: Ericsson-PE-Bangalore-KA-59

ALARM_2319 Severity: Warning

Node: Ericsson-PE-Bangalore-KA-59 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_2319

Description

This SOP outlines the steps to diagnose and resolve the ALARM_2319 warning on the Ericsson Provider Edge Router at Bangalore Node ID: Ericsson-PE-Bangalore-KA-59.

Potential Root Causes

Cause	Probability
Inconsistent BGP configuration between Provider Edge Router and Neighbor AS	Medium
Incorrect IP address configuration on Provider Edge Router interface	Low
BGP session issue due to authentication failure	High

Diagnostic Commands

```
show bgp summary
show ip bgp neighbors
show ip bgp summary | include neighbor-as
show ip interface brief
show bgp neighbors summary
```

Resolution Steps

- Step 1: {'Step': 'Verify BGP configuration consistency', 'Action': 'Run the command `show bgp summary` and ensure that BGP configuration is consistent between Provider Edge Router and Neighbor AS.', 'CLI_Command': 'show bgp summary'}
- Step 2: {'Step': 'Verify IP address configuration', 'Action': 'Run the command `show ip interface brief` and ensure that IP address configuration on Provider Edge Router interface is correct.', 'CLI_Command': 'show ip interface brief'}
- Step 3: {'Step': 'Verify BGP session', 'Action': 'Run the commands `show bgp neighbors summary` and `show bgp neighbors details` to verify BGP session status and troubleshoot any authentication issues.', 'CLI_Commands': ['show bgp neighbors summary', 'show bgp neighbors details']}

Post-Check Verification

```
show bgp summary  
show ip bgp neighbors  
show bgp neighbors summary
```