

Ericsson PE Bangalore KA-59 Alarm ALARM_3664 Resolution SOP

Node: Ericsson-PE-Bangalore-KA-59 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_3664

Description

Minor alarm on Ericsson Provider Edge Router Ericsson-PE-Bangalore-KA-59: ALARM_3664

Potential Root Causes

Cause	Probability
Incorrect configuration of BFD (Bidirectional Forwarding Detection) on the Provider Edge Router	Medium
Hardware failure or degradation in the Provider Edge Router	Low
Software issue or bug in the Provider Edge Router's operating system or applications	Low

Diagnostic Commands

```
show bfd session
show bfd peers
show bfd statistics
show int detail
show ip bdp summary
show ip bgp neighbors
```

Resolution Steps

- Step 1: {'Step': 'Check BFD configuration', 'Action': 'verify bfd configuration is correct and consistent across all interfaces', 'CLI_Command': 'show bfd session'}
- Step 2: {'Step': 'Verify interface status', 'Action': 'check interface status and ensure it is operational', 'CLI_Command': 'show int detail'}
- Step 3: {'Step': 'Check BGP neighbor status', 'Action': 'verify BGP neighbor status and ensure it is established', 'CLI_Command': 'show ip bgp neighbors'}
- Step 4: {'Step': 'Reset BFD', 'Action': 'reset bfd session and restart bfd process', 'CLI_Command': 'clear bfd session'}

Post-Check Verification

```
show bfd statistics
```

```
show int detail
show ip bgp summary
show ip bgp neighbors
```