

Alarm Handling Procedure for Ericsson-PE-Bangalore-KA-59

Node: Ericsson-PE-Bangalore-KA-59 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_4014

Description

This Standard Operating Procedure (SOP) outlines the steps to handle the ALARM_4014 (Warning) on Ericsson-PE-Bangalore-KA-59, a Provider Edge Router.

Potential Root Causes

Cause	Probability
Misconfiguration of BGP routing policy	Medium
Routing protocol issue with neighboring routers	High
Network interface issues (e.g. link down, MTU mismatch)	Low

Diagnostic Commands

```
show bgp summary
show ip bgp neighbors
show interfaces brief
show bgp policy
debug bgp
```

Resolution Steps

- Step 1: {'Step': 'Verify BGP routing policy configuration', 'Action': 'Run command: show bgp policy'}
- Step 2: {'Step': 'Check for routing protocol issues with neighboring routers', 'Action': 'Run command: show ip bgp neighbors'}
- Step 3: {'Step': 'Verify network interface status', 'Action': 'Run command: show interfaces brief'}
- Step 4: {'Step': 'Clear BGP sessions', 'Action': 'Run command: clear bgp * soft'}
- Step 5: {'Step': 'Verify BGP routing table', 'Action': 'Run command: show bgp summary'}

Post-Check Verification

```
show bgp summary
show ip bgp neighbors
```

```
show interfaces brief
```