

# Ericsson PE Bangalore KA-59 Alarm Incident Response SOP

**Node:** Ericsson-PE-Bangalore-KA-59 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM\_5309

## Description

This SOP outlines the procedures to follow when the ALARM\_5309 (Warning) is triggered on the Ericsson Provider Edge Router located at Bangalore KA-59. The ALARM\_5309 is indicative of a potential issue with the router's routing information protocol (RIP) process.

## Potential Root Causes

| Cause                                | Probability |
|--------------------------------------|-------------|
| Router configuration inconsistencies | High        |
| RIP process errors                   | Medium      |
| Software/hardware issues             | Low         |

## Diagnostic Commands

```
show rip database
show rip neighbors
show ip rip statistics
show process cpu
show process memory
```

## Resolution Steps

- Step 1: {'Step': 'Verify router configuration', 'Action': "Run the command 'show running-config' to check for any configuration inconsistencies"}
- Step 2: {'Step': 'Restart the RIP process', 'Action': "Run the command 'clear ip rip process' to restart the RIP process"}
- Step 3: {'Step': 'Check for software/hardware issues', 'Action': "Run the command 'show process cpu' and 'show process memory' to check for any memory leaks or CPU utilization issues"}
- Step 4: {'Step': 'Verify RIP database and neighbors', 'Action': "Run the command 'show rip database' and 'show rip neighbors' to verify the RIP database and neighbors"}

## Post-Check Verification

```
show rip database
```

```
show rip neighbors
show ip rip statistics
show process cpu
show process memory
```