

Standard Operating Procedure for Resolving ALARM_5692 on Ericsson-PE-Bangalore-KA-59

Node: Ericsson-PE-Bangalore-KA-59 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_5692

Description

This SOP outlines the steps to diagnose and resolve ALARM_5692 on Ericsson Provider Edge Router, Ericsson-PE-Bangalore-KA-59. The alarm indicates a critical issue that requires immediate attention.

Potential Root Causes

Cause	Probability
High CPU utilization on the router	High
Memory issues due to software bugs or configuration errors	Medium
Hardware failure or malfunction	Low

Diagnostic Commands

```
show processes cpu | include system
show memory | include statistics
show hardware | include status
```

Resolution Steps

- Step 1: { 'Step': "Run the 'clear system' command to reset the system", 'Description': 'This command will reset the system and clear any pending or stuck processes.', 'CLI_Commands': ['clear system'] }
- Step 2: { 'Step': 'Check and optimize the router configuration', 'Description': 'Verify that the router configuration is optimal and not causing any issues.', 'CLI_Commands': ['show configuration | include optimization'] }
- Step 3: { 'Step': 'Replace faulty hardware', 'Description': 'If the hardware failure is confirmed, replace the faulty component.', 'CLI_Commands': [] }

Post-Check Verification

```
show processes cpu | include system
show memory | include statistics
show hardware | include status
```