

Standard Operating Procedure for ALARM_8733 on Ericsson Provider Edge Router (PE) in Bangalore, KA-59

Node: Ericsson-PE-Bangalore-KA-59 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_8733

Description

Minor Alarm: ALARM_8733 on Ericsson Provider Edge Router (PE) in Bangalore, KA-59. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Misconfigured BGP Peer	Medium
Software Bug in Ericsson PE Firmware	Low
Incorrect Router Configuration	Medium

Diagnostic Commands

```
show bgp summary
show bgp neighbors
show bgp route-distinguisher
show ip bgp
show run | inc bgp
```

Resolution Steps

- Step 1: {'Step': 'Verify BGP neighbor relationships', 'Action': 'Use the show bgp neighbors command to confirm BGP neighbor relationships are established and functioning correctly'}
- Step 2: {'Step': 'Check BGP configuration', 'Action': 'Verify BGP configuration is correct using the show run | inc bgp command and make any necessary adjustments'}
- Step 3: {'Step': 'Restart BGP process', 'Action': 'Use the command "admin restart bgp" to restart the BGP process'}
- Step 4: {'Step': 'Verify BGP routes', 'Action': 'Use the show ip bgp command to verify BGP routes are being propagated correctly'}

Post-Check Verification

```
show bgp summary
show bgp neighbors
show bgp route-distinguisher
show ip bgp
show run | inc bgp
```