

Ericsson PE Router Alarm Resolution SOP

Node: Ericsson-PE-Chennai-TN-83 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_3399

Description

Procedure to resolve ALARM_3399 on Ericsson Provider Edge Router in Chennai, TN-83 site.

Potential Root Causes

Cause	Probability
Invalid routing configuration	High
Network interface flapping	Medium
Software bug or mismatch	Low

Diagnostic Commands

```
show ip int brief
show ip route
show run | inc BGP
show process cpu
show process memory
```

Resolution Steps

- Step 1: {'Step': 'Verify routing configuration', 'Action': 'Check for any invalid or missing routing configurations', 'Command': 'show run | inc BGP'}
- Step 2: {'Step': 'Check network interfaces', 'Action': 'Verify if any network interfaces are flapping', 'Command': 'show ip int brief'}
- Step 3: {'Step': 'Update software or configuration', 'Action': 'Update the software or configuration to the latest version', 'Command': 'install '}
- Step 4: {'Step': 'Restart router', 'Action': 'Restart the router to clear any software or configuration issues', 'Command': 'reload'}

Post-Check Verification

```
show ip int brief
show ip route
show process cpu
show process memory
```