

Ericsson PE Router Alarm Mitigation SOP

(ALARM_3899)

Node: Ericsson-PE-Chennai-TN-83 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_3899

Description

This Standard Operating Procedure (SOP) outlines the steps to mitigate a Minor alarm ALARM_3899 on the Ericsson Provider Edge Router located at Chennai, TN-83.

Potential Root Causes

Cause	Probability
High CPU utilization due to excessive packet processing.	High
Misconfiguration of QoS policies.	Medium
Hardware issues with the router's CPU or memory.	Low

Diagnostic Commands

```
show cpu utilization
show queue statistics
show qos policy
show hardware status
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU utilization and queue statistics.', 'Action': "Run the command 'show cpu utilization' and 'show queue statistics' to identify any patterns or anomalies."}
- Step 2: {'Step': '2. Verify QoS policy configuration.', 'Action': "Run the command 'show qos policy' to ensure that QoS policies are correctly configured and not causing any issues."}
- Step 3: {'Step': '3. Check hardware status.', 'Action': "Run the command 'show hardware status' to identify any hardware issues with the router's CPU or memory."}
- Step 4: {'Step': '4. Adjust QoS policies if necessary.', 'Action': 'Modify QoS policies to prioritize critical traffic if CPU utilization is high or queue statistics indicate congestion.'}
- Step 5: {'Step': '5. Replace hardware if necessary.', 'Action': "Replace the router's CPU or memory if hardware issues are identified."}

Post-Check Verification

```
show cpu utilization
```

```
show queue statistics
```

```
show qos policy
```

```
show hardware status
```