

SOP: Troubleshooting ALARM_4319 on Ericsson Provider Edge Router in Chennai

Node: Ericsson-PE-Chennai-TN-83 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_4319

Description

Alarm ALARM_4319 indicates a minor issue with the Provider Edge Router in Chennai. This SOP outlines the steps to troubleshoot and resolve this alarm.

Potential Root Causes

Cause	Probability
Interface Flapping	Medium
Misconfigured Routing Protocol	High
Physical Layer Issue	Low

Diagnostic Commands

```
show interfaces terse
show ip bgp summary
show routing protocols all
show ip interface brief
```

Resolution Steps

- Step 1: {'Step': 'Check interface configuration', 'Action': "Verify interface settings using 'show interfaces' command"}
- Step 2: {'Step': 'Verify routing protocol configuration', 'Action': "Check routing protocol settings using 'show routing protocols' command"}
- Step 3: {'Step': 'Restart the interface', 'Action': "Use 'interface restart' command"}
- Step 4: {'Step': 'Verify physical layer connectivity', 'Action': "Use 'show interfaces' command to check for any physical layer issues"}
- Step 5: {'Step': 'Clear the routing table', 'Action': "Use 'clear ip routing' command"}

Post-Check Verification

```
show interfaces
show ip bgp summary
show routing protocols all
```

```
show ip interface brief
```