

Ericsson Provider Edge Router Warning Alarm SOP

Node: Ericsson-PE-Chennai-TN-83 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_5382

Description

This SOP outlines the steps to troubleshoot and resolve Alarm Code ALARM_5382 (Warning) on Ericsson Provider Edge Router (Node ID: Ericsson-PE-Chennai-TN-83)

Potential Root Causes

Cause	Probability
High CPU utilization on the router	High
Misconfigured traffic policing policy	Medium
Hardware issues with the router's interface	Low

Diagnostic Commands

```
show cpu utilization
show policy-map interface
show interface
show log | include ALARM_5382
```

Resolution Steps

- Step 1: { 'Step': '1. Check CPU utilization on the router', 'Description': "Run the command 'show cpu utilization' to check the CPU utilization on the router. If CPU utilization is high, proceed to the next step.", 'CLI_Command': 'show cpu utilization' }
- Step 2: { 'Step': '2. Verify traffic policing policy', 'Description': "Run the command 'show policy-map interface ' to verify the traffic policing policy. If the policy is misconfigured, modify it according to the vendor's documentation.", 'CLI_Command': 'show policy-map interface ' }
- Step 3: { 'Step': '3. Check interface hardware', 'Description': "Run the command 'show interface ' to check the interface hardware. If there are any hardware issues, contact the vendor's support team.", 'CLI_Command': 'show interface ' }
- Step 4: { 'Step': '4. Clear the alarm', 'Description': "Run the command 'clear alarm ' to clear the alarm.", 'CLI_Command': 'clear alarm ALARM_5382' }

Post-Check Verification

```
show alarm | include ALARM_5382
```

```
show cpu utilization
show policy-map interface
show interface
```