

Ericsson PE Router - ALARM_8108: Unexpected Packet Loss

Node: Ericsson-PE-Chennai-TN-83 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_8108

Description

Alarm triggered on Ericsson PE Router Node ID: Ericsson-PE-Chennai-TN-83 due to unexpected packet loss, indicating a potential network congestion or interface issue.

Potential Root Causes

Cause	Probability
Network Congestion	High
Interface Misconfiguration	Medium
Hardware Failure	Low

Diagnostic Commands

```
show interfaces
show ip traffic
show ip route
show platform software
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Check interface status and configuration', 'Action': 'Enter the command "show interfaces" to verify interface status and configuration.'}
- Step 2: {'Step': 'Verify routing table and IP traffic', 'Action': 'Enter the command "show ip route" to verify routing table and "show ip traffic" to verify IP traffic.'}
- Step 3: {'Step': 'Check hardware and software status', 'Action': 'Enter the command "show platform software" to verify software status and "show tech-support" to verify hardware status.'}
- Step 4: {'Step': 'Reset or restart the interface', 'Action': 'Enter the command "interface Ethernet " to reset or restart the interface.'}
- Step 5: {'Step': 'Reconfigure interface settings', 'Action': 'Enter the command "interface Ethernet " to reconfigure interface settings.'}

Post-Check Verification

```
show interfaces
show ip traffic
show ip route
show platform software
```