

Ericsson PE Router (Delhi NCR-23) Minor Alarm Resolution SOP

Node: Ericsson-PE-Delhi-NCR-23 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_1384

Description

This SOP outlines the procedures for resolving the Minor alarm ALARM_1384 on the Ericsson Provider Edge Router at Delhi NCR-23.

Potential Root Causes

Cause	Probability
Invalid routing configuration	Medium
BGP session issues with neighboring routers	High
Hardware issues with the Provider Edge Router	Low

Diagnostic Commands

```
show bgp summary
show bgp neighbors
show ip bgp | include ALARM_1384
show system resource
show hardware | include PE-Router
```

Resolution Steps

- Step 1: {'Step': 'Verify BGP sessions', 'Action': "Run the command 'show bgp neighbors' to check for any issues with the BGP sessions."}
- Step 2: {'Step': 'Check routing configuration', 'Action': "Run the command 'show running-config' to verify the routing configuration."}
- Step 3: {'Step': 'Reset BGP sessions', 'Action': "Run the command 'clear bgp *' to reset the BGP sessions."}
- Step 4: {'Step': 'Verify system resources', 'Action': "Run the command 'show system resource' to verify that the system resources are sufficient."}
- Step 5: {'Step': 'Replace faulty hardware', 'Action': 'If the issue is due to hardware issues, replace the faulty hardware with a new one.'}

Post-Check Verification

```
show bgp summary
show bgp neighbors
show ip bgp | include ALARM_1384
show system resource
```