

Standard Operating Procedure for ERICSSON-PE-DELHI-NCR-23

Node: Ericsson-PE-Delhi-NCR-23 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_9155

Description

Alarm ALARM_9155 (Severity: Warning) on Ericsson Provider Edge Router

Potential Root Causes

Cause	Probability
Hardware failure on one of the interface cards	High
Misconfigured VLAN on the affected interface	Medium
Software bug in the Provider Edge Router's operating system	Low

Diagnostic Commands

```
show interface | include err
show vlan | include err
show version | include Software
show system resources | include Memory
```

Resolution Steps

- Step 1: {'Step': '1. Check for hardware failures', 'Action': 'Run the show interface | include err command to check for hardware errors.'}
- Step 2: {'Step': '2. Verify VLAN configuration', 'Action': 'Run the show vlan | include err command to verify VLAN configuration. If misconfigured, correct the VLAN settings.'}
- Step 3: {'Step': '3. Check for software bugs', 'Action': 'Run the show version | include Software command to check for software version and patches. Apply necessary patches and reboot the device if required.'}
- Step 4: {'Step': '4. Check system resources', 'Action': 'Run the show system resources | include Memory command to check for low memory conditions. Add more memory or reboot the device if necessary.'}

Post-Check Verification

```
show interface | include err
show vlan | include err
```

```
show version | include Software  
show system resources | include Memory
```