

Ericsson PE Router Alarm SOP: ALARM_9482

Node: Ericsson-PE-Delhi-NCR-23 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_9482

Description

This Standard Operating Procedure (SOP) outlines the steps to diagnose, resolve, and verify a minor alarm on the Ericsson Provider Edge Router (PE Router) Node ID: Ericsson-PE-Delhi-NCR-23.

Potential Root Causes

Cause	Probability
Invalid routing configuration	Medium
Interface flap due to hardware failure	Low
Software bug or patch conflict	Low

Diagnostic Commands

```
show ip bgp summary
show ip bgp neighbors
show interface status
show system internal alarm
```

Resolution Steps

- Step 1: {'Step': 'Verify routing configuration and correct if necessary', 'Action': 'show run | include route-map'}
- Step 2: {'Step': 'Check interface status and status of neighboring routers', 'Action': 'show interface status'}
- Step 3: {'Step': 'Clear the alarm and restart the interface', 'Action': 'clear ip bgp * > restart interface '}
- Step 4: {'Step': 'Verify that the alarm has cleared', 'Action': 'show system internal alarm'}
- Step 5: {'Step': 'Verify that routing is stable and neighbor relationships are established', 'Action': 'show ip bgp summary'}

Post-Check Verification

```
show system internal alarm
show ip bgp summary
show ip bgp neighbors
```