

SOP: Troubleshooting Alarm ALARM_1688 on Ericsson PE Router

Node: Ericsson-PE-Kolkata-WB-129 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_1688

Description

Warning alarm indicating a potential issue with the Provider Edge Router's functionality.

Potential Root Causes

Cause	Probability
High CPU utilization due to software bugs or configuration issues	High
Memory leak causing insufficient resources for the system	Medium
Misconfigured routing protocols or policies	Low

Diagnostic Commands

```
show cpu utilization
show memory stats
show routing table
show policy statistics
```

Resolution Steps

- Step 1: {'Step': 'Check CPU utilization and adjust if necessary', 'CLI_Command': 'show cpu utilization \n adjust cpu settings if necessary'}
- Step 2: {'Step': 'Monitor system memory and restart if necessary', 'CLI_Command': 'show memory stats \n restart system if memory leak detected'}
- Step 3: {'Step': 'Verify routing protocol and policy configurations', 'CLI_Command': 'show routing table \n show policy statistics \n adjust configurations if necessary'}

Post-Check Verification

```
show cpu utilization
show memory stats
show routing table
show policy statistics
```