

Ericsson PE Router Alarm 1851 Resolution SOP

Node: Ericsson-PE-Mumbai-MH-35 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_1851

Description

This SOP outlines the steps to diagnose and resolve the Ericsson Provider Edge Router Alarm 1851 on Node ID: Ericsson-PE-Mumbai-MH-35.

Potential Root Causes

Cause	Probability
Invalid or missing IP address in routing table	High
Interface or link down	Medium
Routing protocol configuration error	Low

Diagnostic Commands

```
show ip int brief
show ip route
show bgp summary
show ldp neighbors
```

Resolution Steps

Step 1: {'Step': 'Verify IP address in routing table', 'Action': 'Run show ip route command to check IP address', 'CLI_Command': 'show ip route'}

Step 2: {'Step': 'Verify interface status', 'Action': 'Run show ip int brief command to check interface status', 'CLI_Command': 'show ip int brief'}

Step 3: {'Step': 'Verify routing protocol configuration', 'Action': 'Run show bgp summary command to check routing protocol configuration', 'CLI_Command': 'show bgp summary'}

Step 4: {'Step': 'Clear IP routing table', 'Action': 'Run clear ip route * command to clear IP routing table', 'CLI_Command': 'clear ip route *'}

Step 5: {'Step': 'Verify LDP neighbors', 'Action': 'Run show ldp neighbors command to check LDP neighbors', 'CLI_Command': 'show ldp neighbors'}

Post-Check Verification

```
show ip route
show ip int brief
```

```
show bgp summary  
show ldp neighbors
```