

Ericsson Provider Edge Router Alarm SOP - ALARM_2675

Node: Ericsson-PE-Mumbai-MH-35 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_2675

Description

This SOP outlines the steps to diagnose and resolve a major alarm on the Ericsson Provider Edge Router, Node ID: Ericsson-PE-Mumbai-MH-35, Alarm Code: ALARM_2675. The alarm indicates a critical issue with the router's functionality.

Potential Root Causes

Cause	Probability
Router Software Crash	High
Hardware Component Failure	Medium
Misconfigured Router Settings	Low

Diagnostic Commands

```
show version
show system resource
show process cpu
show process memory
show logging messages
```

Resolution Steps

- Step 1: {'Step': 'Restart the Router', 'Description': 'Issue the command ' restart system' to reboot the router. This will resolve software-related issues.', 'CLI_Command': 'restart system'}
- Step 2: {'Step': 'Replace Faulty Hardware', 'Description': 'Replace the faulty hardware component as identified through diagnostic commands.', 'CLI_Command': ''}
- Step 3: {'Step': 'Re-Configure Router Settings', 'Description': 'Verify and re-configure the router settings to ensure they are correct.', 'CLI_Command': 'conf t, then verify and modify settings as needed'}

Post-Check Verification

```
show version
show system resource
show process cpu
```

```
show process memory  
show logging messages
```