

Ericsson Provider Edge Router (PE) Alarm SOP - ALARM_6799

Node: Ericsson-PE-Mumbai-MH-35 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_6799

Description

This SOP outlines the procedure for identifying and resolving the ALARM_6799 issue on the Ericsson Provider Edge Router (PE) node located at Mumbai, MH-35. The alarm is triggered due to a minor issue.

Potential Root Causes

Cause	Probability
Interface flap on the Provider Edge Router	Medium
Misconfigured routing policy	Low
Software bug in the Provider Edge Router	Low

Diagnostic Commands

```
show interface status
show ip bgp summary
show route policy
show system internal alarm
```

Resolution Steps

- Step 1: {'Step': '1. Check the interface status', 'Description': "Verify if the interface is up or down using the 'show interface status' command. If the interface is down, bring it up and retry the command.", 'Command': 'show interface status'}
- Step 2: {'Step': '2. Verify BGP peer status', 'Description': "Check the status of BGP peers using the 'show ip bgp summary' command. Ensure all peers are established.", 'Command': 'show ip bgp summary'}
- Step 3: {'Step': '3. Review routing policy', 'Description': "Analyze the routing policy configuration using the 'show route policy' command. Ensure the policy is correctly configured.", 'Command': 'show route policy'}
- Step 4: {'Step': '4. Clear alarms and restart the system', 'Description': "Clear the alarm using the 'clear system internal alarm' command and restart the system using the 'request system restart' command.", 'Command': 'clear system internal alarm'}

Post-Check Verification

```
show system internal alarm
show interface status
show ip bgp summary
show route policy
```