

Ericsson Provider Edge Router - ALARM_7263 SOP

Node: Ericsson-PE-Mumbai-MH-35 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_7263

Description

Alarm ALARM_7263 indicates a major issue with the Ericsson Provider Edge Router (PE) in Mumbai. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Hardware failure in the line card or route processor	High
Software bug in the router's control plane	Medium
Misconfiguration of the router's BGP peering	Low

Diagnostic Commands

```
show alarm all
show tech-support
show bgp summary
show bgp neighbors
```

Resolution Steps

- Step 1: {'Step': 'Restart the affected line card or route processor', 'CLI_Command': 'restart /LC/0/CPU0'}
- Step 2: {'Step': 'Clear the BGP tables and re-establish peering', 'CLI_Command': 'clear bgp 0.0.0.0/0'}
- Step 3: {'Step': 'Check and correct any software or configuration issues', 'CLI_Command': 'show running-config'}

Post-Check Verification

```
show alarm all
show bgp summary
show bgp neighbors
```