

Standard Operating Procedure for ALARM_1457 on Ericsson-PE-Mumbai-MH-40

Node: Ericsson-PE-Mumbai-MH-40 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_1457

Description

ALARM_1457 on Ericsson-PE-Mumbai-MH-40 indicates a critical issue with the Provider Edge Router. The alarm is triggered due to a fault in the router's control plane processing unit.

Potential Root Causes

Cause	Probability
Hardware fault in the Control Plane Processing Unit (CPPU)	High
Software issue in the router's control plane software	Medium
Misconfiguration of the router's control plane settings	Low

Diagnostic Commands

```
show system status
show control-plane processing-unit status
show system logs | include ALARM_1457
```

Resolution Steps

- Step 1: {'Step': 'Check the system logs for the ALARM_1457', 'Action': 'show system logs | include ALARM_1457', 'CLI_Commands': ['show system logs | include ALARM_1457']}
- Step 2: {'Step': 'Verify the CPPU status', 'Action': 'show control-plane processing-unit status', 'CLI_Commands': ['show control-plane processing-unit status']}
- Step 3: {'Step': 'Power cycle the CPPU', 'Action': 'system reboot processing-unit cppu', 'CLI_Commands': ['system reboot processing-unit cppu']}
- Step 4: {'Step': 'Check for software issues', 'Action': 'show system software status', 'CLI_Commands': ['show system software status']}
- Step 5: {'Step': 'Install software patches if necessary', 'Action': 'software install patch [patch-number]', 'CLI_Commands': ['software install patch [patch-number]']}
- Step 6: {'Step': 'Verify the control plane settings', 'Action': 'show system configuration control-plane', 'CLI_Commands': ['show system configuration control-plane']}
- Step 7: {'Step': 'Correct the control plane settings if necessary', 'Action': 'system configure control-plane [new-settings]', 'CLI_Commands': ['system configure control-plane [new-settings]']}

Post-Check Verification

```
show system status  
show control-plane processing-unit status  
show system logs | include ALARM_1457
```