

Ericsson PE Router Alarm Resolution SOP

(ALARM_5655)

Node: Ericsson-PE-Mumbai-MH-40 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_5655

Description

This SOP outlines the steps for resolving a major alarm on the Ericsson Provider Edge Router (PE) in Mumbai, Node ID: Ericsson-PE-Mumbai-MH-40.

Potential Root Causes

Cause	Probability
Hardware failure in the router's control plane	High
Software bug or misconfiguration	Medium
Environmental factors such as overheating or power failure	Low

Diagnostic Commands

```
show system redundancy status
show system alarm-history
show system process cpu
show system memory
```

Resolution Steps

- Step 1: {'Step': '1. Power cycle the router', 'Description': 'Perform a power cycle of the router to reset the system and clear any temporary issues.'}
- Step 2: {'Step': '2. Run diagnostic commands', 'Description': 'Run the diagnostic commands listed above to identify any underlying issues.', 'Commands': ['show system redundancy status', 'show system alarm-history', 'show system process cpu', 'show system memory']}
- Step 3: {'Step': '3. Check and replace faulty hardware', 'Description': 'If the root cause is identified as a hardware failure, check the affected components and replace them as necessary.'}
- Step 4: {'Step': '4. Review and update software or configuration', 'Description': 'If the root cause is identified as a software bug or misconfiguration, review and update the software or configuration to resolve the issue.'}
- Step 5: {'Step': '5. Perform environmental checks', 'Description': 'Verify that the environmental factors such as temperature and power supply are within normal operating ranges.'}

Post-Check Verification

```
show system alarm-history
show system redundancy status
show system process cpu
show system memory
```