

SOP: Resolving Major Alarm ALARM_8618 on Ericsson Provider Edge Router Ericsson-PE-Mumbai-MH-40

Node: Ericsson-PE-Mumbai-MH-40 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_8618

Description

Major Alarm ALARM_8618 indicates a significant issue on the Ericsson Provider Edge Router Ericsson-PE-Mumbai-MH-40. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Network Congestion	Medium
Software Bug	Low

Diagnostic Commands

```
show cpu utilization
show interface counters
show ip bdp summary
show system resources
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU Utilization', 'Action': "Run the command 'show cpu utilization' to check the current CPU utilization. If it's above 80%, proceed to the next step.", 'CLI_Command': 'show cpu utilization'}
- Step 2: {'Step': '2. Verify Network Congestion', 'Action': "Run the command 'show interface counters' to check for any network congestion issues. If found, optimize the network configuration if possible.", 'CLI_Command': 'show interface counters'}
- Step 3: {'Step': '3. Update Software', 'Action': 'Check for any software updates and apply them to the router if available.', 'CLI_Command': 'upgrade software'}
- Step 4: {'Step': '4. Restart the Router', 'Action': 'Restart the router to clear any temporary issues. This should be done after updating the software.', 'CLI_Command': 'restart'}

Post-Check Verification

```
show cpu utilization
show interface counters
show ip bgp summary
show system resources
```