

Ericsson Provider Edge Router SOP for Alarm Code ALARM_2282

Node: Ericsson-PE-Mumbai-MH-45 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_2282

Description

This SOP outlines the steps to diagnose and resolve the Ericsson Provider Edge Router alarm ALARM_2282, a minor issue.

Potential Root Causes

Cause	Probability
Incorrect routing protocol configuration	Medium
Faulty routing protocol process	High
Insufficient memory or resources	Low

Diagnostic Commands

```
show ip bgp summary
show ip bgp neighbors
show process CPU usage
show memory | include free
debug ip bgp
```

Resolution Steps

Step 1: {'Step': 'Check and correct routing protocol configuration', 'Action': "Verify and adjust routing protocol configuration using the following CLI commands: 'show run | include bgp' and 'config t; bgp router-id'", 'CLI_Commands': 'show run | include bgp'}

Step 2: {'Step': 'Restart routing protocol process', 'Action': "Use the CLI command 'process restart bgp' to restart the BGP process", 'CLI_Commands': 'process restart bgp'}

Step 3: {'Step': 'Increase memory or resources', 'Action': 'Verify system resources and allocate additional memory or resources as necessary', 'CLI_Commands': 'show memory'}

Post-Check Verification

```
show ip bgp summary
show ip bgp neighbors
show process CPU usage
```