

Ericsson PE Minor Alarm 4064 SOP

Node: Ericsson-PE-Mumbai-MH-45 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_4064

Description

This SOP outlines the steps to diagnose, resolve, and verify a minor alarm 4064 on the Ericsson Provider Edge Router in Mumbai.

Potential Root Causes

Cause	Probability
Invalid P2MP VLAN configuration	High
Misconfigured EVPN multi-homing	Medium
Faulty network interface	Low

Diagnostic Commands

```
show p2mp vlan config
show evpn multi-homing status
show interface status
```

Resolution Steps

- Step 1: {'Step': 'Verify P2MP VLAN configuration', 'Action': "Run the command 'show p2mp vlan config' to verify the configuration.", 'Command': 'config p2mp vlan'}
- Step 2: {'Step': 'Correct EVPN multi-homing configuration', 'Action': "Run the command 'config evpn multi-homing' to correct the configuration.", 'Command': 'config evpn multi-homing'}
- Step 3: {'Step': 'Replace faulty network interface', 'Action': 'Replace the faulty network interface with a new one.', 'Command': 'replace interface'}

Post-Check Verification

```
show p2mp vlan config
show evpn multi-homing status
show interface status
```