

SOP - Ericsson Provider Edge Router ALARM_5300

Node: Ericsson-PE-Mumbai-MH-45 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_5300

Description

ALARM_5300 on Ericsson-PE-Mumbai-MH-45: Minor alarm indicating possible packet loss or mis-delivery issue.

Potential Root Causes

Cause	Probability
Misconfigured or faulty interface	High
Network congestion or high latency	Medium
Software or firmware issues	Low

Diagnostic Commands

```
show interface status
show ip interface brief
show ip routing table
show ip bgp summary
show system log | include ALARM_5300
```

Resolution Steps

- Step 1: {'Step': '1. Identify the affected interface', 'Action': 'Use the show interface status command to identify the interface causing the alarm.'}
- Step 2: {'Step': '2. Verify interface configuration', 'Action': 'Use the show interface [interface-name] command to verify interface configuration.'}
- Step 3: {'Step': '3. Check for network congestion', 'Action': 'Use the show ip bgp summary command to check for network congestion or high latency.'}
- Step 4: {'Step': '4. Firmware or software update', 'Action': 'Check for any available firmware or software updates and apply them if necessary.'}

Post-Check Verification

```
show interface status
show ip interface brief
show ip routing table
```