

Ericsson Provider Edge Router (PER) Minor Alarm Resolution SOP

Node: Ericsson-PE-Mumbai-MH-45 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_9540

Description

This SOP outlines the steps to diagnose and resolve the minor alarm ALARM_9540 on Ericsson Provider Edge Router (PER) Node ID: Ericsson-PE-Mumbai-MH-45.

Potential Root Causes

Cause	Probability
Misconfigured BGP Peer	High
Interface flap due to hardware issues	Medium
Software bug in the PER	Low

Diagnostic Commands

```
show bgp peer-group detail
show interface detail
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Verify BGP peer configuration', 'Command': 'show bgp peer-group detail'}
- Step 2: {'Step': 'Check interface for hardware issues', 'Command': 'show interface detail'}
- Step 3: {'Step': 'Reset the BGP peer', 'Command': 'clear bgp peer-group '}
- Step 4: {'Step': 'Reload the PER', 'Command': 'reload'}

Post-Check Verification

```
show bgp peer-group detail
show interface detail
show bgp summary
```