

Standard Operating Procedure for Resolving ALARM_2970 on Ericsson PE Router

Node: Ericsson-PE-Mumbai-MH-47 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_2970

Description

ALARM_2970 on Ericsson PE Router is a critical alarm indicating a potential hardware failure or configuration mismatch.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Configuration Mismatch	Medium
Software Bug	Low

Diagnostic Commands

```
show system internal alarm detailed
show system internal alarm history
show hardware status
show config | i alarm
```

Resolution Steps

- Step 1: {'Step': '1. Check Hardware Status', 'Action': "Run 'show hardware status' command to identify any hardware issues."}
- Step 2: {'Step': '2. Check Configuration', 'Action': "Run 'show config | i alarm' command to verify alarm configuration."}
- Step 3: {'Step': '3. Restart Router', 'Action': "Run 'system restart' command to reboot the router."}
- Step 4: {'Step': '4. Verify Alarm Status', 'Action': "Run 'show system internal alarm detailed' command to verify alarm status."}
- Step 5: {'Step': '5. Replace Hardware (if necessary)', 'Action': 'Replace faulty hardware component.'}

Post-Check Verification

```
show system internal alarm detailed
show system internal alarm history
```