

Ericsson Provider Edge Router Alarm SOP - ALARM_8590

Node: Ericsson-PE-Mumbai-MH-47 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_8590

Description

This SOP outlines the steps to diagnose and resolve the ALARM_8590, a minor alarm on the Ericsson Provider Edge Router node Ericsson-PE-Mumbai-MH-47.

Potential Root Causes

Cause	Probability
Link Down	Medium
Neighbor not responding	High
Misconfiguration of the interface	Low

Diagnostic Commands

```
show ip int brief
show ip bgp summary
show run | inc interface
show ip bgp neighbors
```

Resolution Steps

- Step 1: {'Step': 'Verify the link status', 'Action': 'Use the command show ip int brief to verify the link status. If the link is down, proceed to the next step.', 'CLI_Command': 'show ip int brief'}
- Step 2: {'Step': 'Verify the neighbor status', 'Action': 'Use the command show ip bgp neighbors to verify the neighbor status. If the neighbor is not responding, proceed to the next step.', 'CLI_Command': 'show ip bgp neighbors '}
- Step 3: {'Step': 'Verify the interface configuration', 'Action': '"Use the command show run | inc interface to verify the interface configuration. If the configuration is incorrect, update the configuration according to the vendor's guidelines."', 'CLI_Command': 'show run | inc interface'}
- Step 4: {'Step': 'Reset the interface', 'Action': 'Use the command clear ip int to reset the interface. If the issue persists, escalate the issue to the network operations team.', 'CLI_Command': 'clear ip int '}

Post-Check Verification

```
show ip int brief
show ip bgp summary
```

```
show ip bgp neighbors  
show run | inc interface
```