

Ericsson Provider Edge Router (PE) Issue Resolution SOP

Node: Ericsson-PE-Mumbai-MH-47 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_9045

Description

This SOP outlines the procedures for resolving the ALARM_9045 on the Ericsson Provider Edge Router (PE) in Mumbai, India.

Potential Root Causes

Cause	Probability
Misconfigured VPN Routing Instance	High
Interface Flapping or Unstable Link	Medium
Software or Firmware Issues	Low

Diagnostic Commands

```
show vpn routing-instance
show interface detail
show system software version
show system firmware version
```

Resolution Steps

- Step 1: {'Step': '1. Verify VPN Routing Instance Configuration', 'Action': "Run the command 'show vpn routing-instance ' to verify the configuration.", 'CLI_Command': 'show vpn routing-instance '}
- Step 2: {'Step': '2. Check Interface Status', 'Action': "Run the command 'show interface detail' to verify the interface status.", 'CLI_Command': 'show interface detail'}
- Step 3: {'Step': '3. Update Software or Firmware', 'Action': 'Update the software or firmware to the latest version if necessary.', 'CLI_Command': 'software update install '}
- Step 4: {'Step': '4. Reboot the Device', 'Action': 'Reboot the device to apply the changes.', 'CLI_Command': ' reboot'}

Post-Check Verification

```
show vpn routing-instance detail
show interface detail
show system software version
```

```
show system firmware version
```