

Huawei Access Switch Alarm Resolution:

ALARM_1060

Node: Huawei-Access-Bangalore-KA-66 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_1060

Description

This SOP outlines the steps to diagnose and resolve ALARM_1060 on Huawei Access Switch Node ID: Huawei-Access-Bangalore-KA-66.

Potential Root Causes

Cause	Probability
Optical module failure	High
Incorrect optical fiber connection	Medium
Temperature or humidity issues	Low

Diagnostic Commands

```
display version
display diagnostic information
show optical module status
```

Resolution Steps

- Step 1: {'Step': 'Check the optical module status', 'Action': "Use the command 'show optical module status' to identify the faulty optical module."}
- Step 2: {'Step': 'Disconnect and reconnect the optical fibers', 'Action': 'Verify the optical fibers are securely connected to the correct ports on the switch and the optical module.'}
- Step 3: {'Step': 'Replace the faulty optical module', 'Action': 'Replace the faulty optical module with a new one and verify the alarm is cleared.'}
- Step 4: {'Step': 'Verify the temperature and humidity levels', 'Action': "Use the command 'display environment monitoring status' to verify the temperature and humidity levels are within the recommended range."}

Post-Check Verification

```
display alarm-info
display diagnostic information
show optical module status
```