

Huawei Access Switch - ALARM_9946 Warning Alarm Resolution SOP

Node: Huawei-Access-Bangalore-KA-68 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_9946

Description

This Standard Operating Procedure (SOP) outlines the steps to resolve the ALARM_9946 warning alarm on Huawei Access Switch Node ID: Huawei-Access-Bangalore-KA-68.

Potential Root Causes

Cause	Probability
Incorrect configuration of the switch's management interface	Medium
Faulty or loose connections to the switch's management interface	High
Software bug or version mismatch	Low

Diagnostic Commands

```
display current-configuration | include management-interface
display device
display version
```

Resolution Steps

- Step 1: {'Step': '1. Verify the management interface configuration', 'Action': 'Check the current configuration for any incorrect settings', 'CLI_Commands': 'display current-configuration | include management-interface'}
- Step 2: {'Step': '2. Check the management interface connections', 'Action': 'Verify that the connections are secure and not loose', 'CLI_Commands': ''}
- Step 3: {'Step': '3. Update the switch software to the latest version', 'Action': 'Check for any software updates and apply them according to the vendor's instructions', 'CLI_Commands': 'display version, system-view, system switchover'}

Post-Check Verification

```
display current-configuration | include management-interface
display device
display version
```