

Huawei Access Switch Alarm Resolution SOP

(ALARM_1412)

Node: Huawei-Access-Chennai-TN-100 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_1412

Description

This SOP outlines the steps to resolve the ALARM_1412 (Minor) on Huawei Access Switch Node ID: Huawei-Access-Chennai-TN-100.

Potential Root Causes

Cause	Probability
Port fault or misconfiguration	High
Cable issue or fault	Medium
Switch software or firmware issue	Low

Diagnostic Commands

```
display current-configuration | include GigabitEthernet1/0/1
display fault GigabitEthernet1/0/1
display environment temperature
```

Resolution Steps

- Step 1: { 'Step': '1. Check Port Configuration and Fault', 'Description': 'Verify the port configuration and check for any faults using the "display current-configuration" and "display fault" commands.', 'CLI_Commands': ['display current-configuration | include GigabitEthernet1/0/1', 'display fault GigabitEthernet1/0/1'] }
- Step 2: { 'Step': '2. Check Cable and Connection', 'Description': 'Verify the cable and connection to the port, check for any signs of physical damage or issues.', 'Actions': ['Inspect the cable and connection'] }
- Step 3: { 'Step': '3. Update Switch Software or Firmware', 'Description': 'Check for any available software or firmware updates and apply them to the switch.', 'CLI_Commands': ['system-view', 'system software auto-install', 'system software install'] }

Post-Check Verification

```
display fault GigabitEthernet1/0/1
display current-configuration | include GigabitEthernet1/0/1
display environment temperature
```