

Huawei Access Switch - Alarm ALARM_1778 SOP

Node: Huawei-Access-Chennai-TN-100 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_1778

Description

Alarm ALARM_1778 indicates a warning condition on Huawei Access Switch Node ID: Huawei-Access-Chennai-TN-100.

Potential Root Causes

Cause	Probability
Invalid configuration of VLAN	High
Loopback detected on a port	Medium
VLAN Trunk Protocol (VTP) issues	Low

Diagnostic Commands

```
display current-configuration | include vlan
display interface {interface_id} verbose
display vtp status
```

Resolution Steps

- Step 1: {'Step': 'Verify VLAN configuration', 'Action': 'Check the VLAN configuration on the switch and on connected devices.', 'CLI_Command': 'display current-configuration | include vlan'}
- Step 2: {'Step': 'Check for loopback', 'Action': 'Verify that loopback is not detected on any port.', 'CLI_Command': 'display interface {interface_id} verbose'}
- Step 3: {'Step': 'Check VTP status', 'Action': 'Verify that VTP is operational and configured correctly.', 'CLI_Command': 'display vtp status'}
- Step 4: {'Step': 'Reset VLAN configuration to default', 'Action': 'Reset VLAN configuration to default settings.', 'CLI_Command': 'reset vlan'}
- Step 5: {'Step': 'Verify VLAN trunk protocol is operational', 'Action': 'Verify that VLAN trunk protocol is operational and configured correctly.', 'CLI_Command': 'display vtp status'}

Post-Check Verification

```
display current-configuration | include vlan
display interface {interface_id} verbose
display vtp status
```